



Second step take the Real Power (MW) and Apparent power (MVA) and find the Power Factor (p.f.)

$$\text{p.f.} = \frac{\text{Real power}}{\text{Apparent power}}$$

$$\text{p.f.} = \frac{56.50}{64.78}$$

$$\text{p.f.} = 0.872$$

